

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee:

Kusumoto et al.

Examiner:

P. Patel

Patent No.:

6,987,383

Group Art Unit:

2829

Issued:

January 17, 2006

Docket No.:

10873.644US01

Title:

SEMICONDUCTOR DEVICE HAVING A CONNECTION INSPECTING CIRCUIT FOR INSPECTING CONNECTION OF POWER SOURCE TERMINALS AND GROUNDING TERMINALS, AND INSPECTION

METHOD FOR THE SAME

CERTIFICATE UNDER 37 CFR 1.6(d):

I hereby certify that this paper is being transmitted by facsimile to the U.S. Patent and Trademark Office on

April 14, 2006.

## REOUEST FOR CERTIFICATE OF CORRECTION

Attn: Certificate of Corrections Branch

Commissioner for Patents

PO Box 1450

Alexandria, VA 22313

Certificate

APR 2 4 2006

of Correction

Dear Sir:

It is requested a Certificate of Correction be issued correcting printing errors appearing in the above-identified United States patent. A copy of the text of the Certificate in the suggested form is attached.

Issuance of the Certificate of Correction would neither expand nor contract the scope of the claims, and re-examination is not required.

Since none of the errors are Patentees' mistake, no fee is believed to be due.

53148

PATENT TRADEMARK OFFICE

Respectfully submitted,

HAMRE, SCHUMANN, MUELLER & LARSON P.C.

P.O. Box 2902

Minneapolis, MN 55402

Telephong: (612) 455-3800

th 14,200

Douglas P. Mueller

Reg. No. 30,300

DPM:unt

Approved for use through 04/30/2007. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

CERTIFICATE OF CORRECTION	:	
	:	
PATENT NO. : 6,987,383	Page 1 of _	1_
APPLICATION NO.: 09/773,502	•	
ISSUE DATE : January 17, 2006	:	
INVENTOR(S) : Kusumoto et al.		
It is certified that an error appears or errors appear in the above-identified patent and the is hereby corrected as shown below:	at said Letters Pa	atent
Front page, (56) References Cited: "JP 10-213633" should readJP 10-213633 *		
	•	
	•	
	,	
	•	
	:	
	•	

MAILING ADDRESS OF SENDER (Please do not use customer number below):

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450. VA 22313-1450.

N 09/773,502

**PATENT** 

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee:

Kusumoto et al.

Examiner:

P. Patel

Patent No.:

6,987,383

Group Art Unit:

2829

53148

PATENT TRADEMARK OFFICE

Issued:

January 17, 2006

Docket No.:

10873.644US01

Title:

SEMICONDUCTOR DEVICE HAVING A CONNECTION INSPECTING CIRCUIT FOR INSPECTING CONNECTION OF POWER SOURCE

TERMINALS AND GROUNDING TERMINALS, AND INSPECTION

METHOD FOR THE SAME

CERTIFICATE UNDER 37 CFR 1.6(d):

I hereby certify that this paper is being transmitted by facsimile to the U.S. Patent and Trademark Office on

April 14, 2006.

Name Liyen Tang

Attn: Certificate of Corrections Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Sir:

The following papers are transmitted herewith:

☐ Transmittal Sheet in duplicate containing Certificate of Mailing

Request for Certificate of Correction

PTO Form/SB/44

Return Postcard

Please charge any additional fees or credit overpayment to Deposit Account No. 50-3478. A duplicate of

this sheet is enclosed.

Hamre, Schumann, Mueller & Larson, P.C. P.O. Box 2902-0902 Minneapolis, MN 55402 612.455-3800

Name: De

Name: Dduglas P. Mueller

Reg. No.: 30,300 Initials: DPM/unt

/N 09/773,502

**PATENT** 

# IN THE <u>UNITED STATES PATENT AND TRADEMARK OFFICE</u>

Patentee:

Kusumoto et al.

Examiner:

P. Patel

Patent No.:

6,987,383

Group Art Unit:

2829

53148

PATENT TRADEMARK OFFICE

Issued:

January 17, 2006

Docket No.:

10873.644US01

Title:

SEMICONDUCTOR DEVICE HAVING A CONNECTION INSPECTING CIRCUIT FOR INSPECTING CONNECTION OF POWER SOURCE

TERMINALS AND GROUNDING TERMINALS, AND INSPECTION

METHOD FOR THE SAME

CERTIFICATE UNDER 37 CFR 1.6(d):

I hereby certify that this paper is being transmitted by facsimile to the U.S. Patent and Trademark Office on

April 14, 2006.

Name Uyen Tang

Attn: Certificate of Corrections Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Sir:

The following papers are transmitted herewith:

Transmittal Sheet in duplicate containing Certificate of Mailing

Request for Certificate of Correction

 $\boxtimes$ PTO Form/SB/44

X Return Postcard

Please charge any additional fees or credit overpayment to Deposit Account No. 50-3478. A duplicate of

this sheet is enclosed.

Hamre, Schumann, Mueller & Larson, P.C. P.O. Box 2902-0902 Minneapolis, MN 55402 612.455-3800

Name: Douglas P. Mueller

Reg. No.: \30,300 Initials: DPM/unt